

NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to N.J.A.C. 7:26-2.12)

Date of Notification (1) 07/07/16			Name of Building Owner/Operator (2) Calpine New Jersey Generation LLC		
Agencies Notified (X) EPA () DEP (X) DOL (X) DOH () DCA		Notification Type () Initial Notification (X) Amended Certification () Cancelled		Street Address 717 Texas Ave, Suite 1000 City, State, Zip Code Houston, TX 77002-2743	
		Name of Contact Paul Ostberg		Tel. Number 856-678-1725	
FACILITY INFORMATION					
Name of Facility Where Abatement is Taking Place (3) Calpine New Jersey Generation LLC			Type of Facility (4) () School (K-12) () Subchapter 8 (other than K-12) (X) Other (i.e. private & commercial bldgs., homes, etc.)		
Street Address 373 N. Broadway			Sq. Feet 97,850 # of Floors 8		
City (5) Pennsville	County (6) Salem	County Code (7) (State Use Only)	Bldg. Age 55 Current Use (prior if being demolished) Power Plant		
Name of Monitoring Firm Hired by Bldg. Owner (8) Horizon Environmental Group		ASCM No. 00073		Name of Contractor (9) Brandenburg Industrial Service Company	
Street Address PO Box 316			Street Address 2217 Spillman Dr		
City, State, Zip Code Thorofare, NJ 08086			City, State, Zip Code Bethlehem Pennsylvania 18015		
Project Manager for Monitoring Firm Steve Flanigan		Telephone Number 856-848-0800		License Number 00721	
Scheduled Start Date (10) 07/18/16		Scheduled Completion Date (11) 03/03/17		Name of OSHA Monitor Brandenburg Industrial Service Company	
Occupancy Status During Abatement (Check only one) (x) Facility Closed/Vacated During Entire Period of Abatement () Abatement Performed Outside of Normal Facility Hours -			Street Address 2217 Spillman Drive		
Describe Demolition (x) Scheduled Demo Start 07/11/16 Scheduled Demo Completion 09/29/17			City, State, Zip Code Bethlehem, PA 18015		
Source of Work (Check all that apply) (x) Demolition () Renovation (x) Large Proj. (>160 SF or >260 LF ACM) () SM Proj. (>25<160 SF or >10 <260 LF ACM) () Minor Proj. (<25 SF or <10 LF ACM) (x) Full Containment with Negative Pressure (x) Mini-Enclosure (x) Glovebag Procedure					
Location of Asbestos-Containing Material (ACM) in Facility (13)		Is Location Normally Used Solely by Maint./Custodial Staff? (12) YES NO NA		Description of ACM (i.e. thermal systems insulation, surfacing, VAT, or other miscell.)	
				Amount (Specify SF or LF)	
				Abatement Type Rem. Rep. Encap Enclose	
Plant Boilers		x		Insulation 80,000 sf x	
Plant Boilers		x		Fire Brick 24,000 sf x	
Main Plant		x		Pipe Insulation 12,500 lf x	
Main Plant		x		Transite/Galbestos 29,265 sf x	
Main Plant		x		VAT 53,000 sf x	
Main Plant		x		Flashing/Tar Paper 64,100 sf x	
Main Plant		x		Caulk/Exp Jt 13,570 sf x	
Pipe Rack		x		Pipe Insulation 9,520 lf x	
Conveyor		x		Galbestos 8,000 sf x	
Misc Small Out Bldgs		x		Caulk/Exp Jt 33,000 sf x	
Misc Small Out Bldgs		x		Transite/Galbestos 4,450 sf x	
Misc Small Out Bldgs		x		Insulation 2,840 sf x	
Name of Reg. Waste Hauler Brandenburg Industrial Serv Co		NJDEP Waste Hauler ID # 21838		Cubic Yards of Waste 15,000 cy	
City, State Bethlehem, PA		Disp. Date TBD		Name of Reg. Landfill Waste Management - Tullytown Landfill City, State Bethlehem, PA	


or Type)

Title

Signature

Date

Contract Manager



07/07/16

Mail to: NJDEP-DSHW-BR RTP
401 E. State St., PO 414
Trenton, NJ 08625-0414

Telephone 609-984-6620

C:\WORD\MYDOCS\ASBESTOS
9/18/00